Work Order ID 57352 April 6, 2010 8:20:42 AM Page 1 Item ID: D3873-1 Accept Revision ID: Setup Start Item Name: Bushing Start Date: 06/04/2010 Stop Start Qty: 40.00 Required Date: 09/04/2010 Cust Item ID: Req'd Qty: 40.00 Reference: Customer: Approvals: Process Plan: Date: 10-4-06 Tooling: Run Start Date: QC: Date: SPC (Y/N): Stop Date: Sequence ID/ Operation Work Center ID Set Up/ Description Draw Draw Plan Reject Accept Run Hours Reject Draw Nbr Number Insp. Rev. Revision Nbr Code Qty Qty Number Stamp 100 0.00 Memo 0.00 Hardinge CNC Lathe Small I-TURN AS PER FOLIO FA806 & DWG D3873 , FOLIO REV: DWG REV:\_ 2-DEBURR AS REQUIRED 110 QC2- Inspect parts off machine FAI/FAIB 0.00 Memo 0.00 Quality Control

5/2 10/04/06

Dart Aerosp	ace	Ltd
-------------	-----	-----

W/O:			WORK ORDER CH					NGES						
DATE	STEP	PR	OCEDURE CH	ANGE	Ву	D	ate	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
									- roomg					
Part No	:	PAR #:	Fault Cate	egory:	NCR: Ye	s No	DQA:		_ Date: _	-24				
	R	esolution:	Disposition	on:	QA: N/C	Close	d:		Date: _					
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NO	CR)								
DATE	STEP	Description of NC		ction B Verif			on	Approval	Approval					
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sigi Da	1 &	Section (		Chief Eng	QC Inspector				
										-1				
									3	1 3				
		4						-						

## Work Order ID 57352

April 6, 2010 8:20:42 AM



Page 2

Item ID:

D3873-1

Revision ID:

Item Name:

Bushing

Start Date:

06/04/2010

Required Date: 09/04/2010

Start Qty: 40.00 Req'd Qty: 40.00

Reference:

Accept



Setup Start

Stop



Cust Item ID:

Plan

Code

Customer:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Draw

Rev.

Start

Reject

Qty

Stop

Reject

Number



QC:

Date:

SPC (Y/N):

Date:

Accept

Qty

Run

Insp.

Stamp

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

0.00

Set Up/ Run Hours 0.00

MUK 10/04/06

Number

Draw

40

130



Packaging

Identify as per dwg & Stock Location: 093

Memo

0.00

0.00

140

Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

D	ar	t /	Aei	ros	pa	ce	Ltc	ł
_		• •		-	Pu		Per # P	•

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PROC	EDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:							4 3
	R	esolution:	Disposition	on:	QA: N/C Clo	sed:		_ Date: _	1
NCR:		Wo	ORK ORD	ER NON-CONFORMA	NCE (NCR)				
DATE	STEP	Description of NC	Corrective Action Section		Verifica	ation	Approval	Approval	
DAIL	OTE	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sectio		Chief Eng	QC Inspector
									19
								45	
									3

## **Picklist Print**

April 6, 2010 8:20:47 AM

Work Order ID: 57352

Parent Item: D3873-1

Parent Item Name: Bushing

Comments:

 (() )(#29) ((8) (8)

Start Date: 06/04/2010

Required Date: 09/04/2010

Component Item ID/	Replacement	Mfg/	Bin	D'					Start Qty: 40.0	0	Required Qty:	
M303R0.750	Item ID	Purch		Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on	Remaining	Qty	Date	
	1111 18881 BUIL BRILLIAN	Purchased	No			100	cusure	Hand	Qty To Pick	Issued	Issued	Status
						100	f	89,9000	2,4000			

303 Round Bar 0.750

Warehouse Location	Loc Oty	Loc Code
Main Warehouse		
MAT028	89.9	
113134	. 7/ 74	
113365	3.9	
<b>-</b> 113424	12	

27/tt 5 N10/04/06

Dart Aerospace Ltd	Dart	Aeros	pace	Ltd
--------------------	------	-------	------	-----

W/O:			V	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							2		
Part No		PAR #:							
	R	esolution:						Date:	
NCR:		V	VORK ORI	DER NON-CONFORM	ANCE (NCR	)			
DATE STEP Description of NC					ion B	Verific	eation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
					_				
									-1
									Ž.
		20							


DART AEROSPACE LTD	Work Order:	57352
Description: Bushing		01001
	Part Number:	D3873-1
Inspection Dwg: D3873 Rev: A		
		Page 1 of 1

Drawing		Actu	Article			otype		
Dimension	Tolerance	Dimen	Λ	ccept	Reject	Method o	of	Comments
Ø0.305	+0.000/-0.002	0)3,	E	/		mopectio	"	
Ø0.191	+0.005/-0.001	00,10	2					
Ø0.63	+/-0.030	10.20	T	-				
0.060	+/-0.005	-06	és i	1				4 30
0.600	+/-0.010	. 55	5					
R0.010	+/-0.010	RO	1					70.15
0.030 x 20°	+/-0.010 x 0.5°	030 X	200					1 1
		0304	20 /		-			- Brank
				-				
								1.044
								1100
							_	
				_				
								-
								4
110								
								(17)
								2002
								47477
			-					
				+				
red by:						1		
3,1	Aud	lited by:	MV=		Pro	ototype App		
Date: 100	406	Date:		00		Totype App	Date:	N/A

Dart Aerospa	ace Lt	d
--------------	--------	---

W/O:		WORK ORDER CHANGES									
DATE	STEP					Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									* . · .		
Part No: PAR #:											
				_ Disposition: Q/							
NCR:				R NON-CONFORM	MANCE	(NCR	)				
DATE	STEP	Description of NC Section A	Initial	Initial Action Description				cation on C	Approval Chief Eng	Approval QC Inspector	
		19	Chief Eng	Chief Eng		Sign & Date	360	on C	Offier Eng	GC Inspector	
				F-							

<sup>-</sup> H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



## Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egory:	NCR	: Yes N	lo DQ/	\	Date:	
			Disposition: Q							
NCR:		1	WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC	Corrective Action Section				Verification		Approval	Approval
	OIL!	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		on C	Chief Eng	QC Inspector
										. 3
									-	
										9
										-
										· ·
										3